

Fig. 1

TUQ9044XXX




Fig. 2

TUQ5057XXX







Fig. 3

TUQ7057XXX







Fig. 4

TUQ7257XXX






Fig. 5

TUQA057XXX








Fig. 6

TUQ3058XXX











Fig. 7




TUQ5058XXX



▶ ORANGE
 ◀ GREEN

Fig. 8

TUQ3088XXX



—▶— ORANGE
—▷— GREEN

Fig. 9

TUQ4088XXX






Fig. 10

TUQ5088XXX






Fig. 11

TUQ5288XXX







Fig. 12

TUQ20GGXXX



➤ SUPER RED
 ➤ SUPER GREEN

COL. PIN	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
ROW PIN	33	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17
1	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
2	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
3	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
4	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
5	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
6	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
7	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
8	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
9	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
10	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
11	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
12	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
13	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
14	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
15	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕
16	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕	↕

Fig. 13

TUQ32GGXXX

